

CAUTION SIGNS FOR ALL OCCASIONS

SAFETY HAZARDS LURK IN EVERY CORNER OF MOTOR POOLS AND MACHINE SHOPS.



BUT A FEW WELL-PLACED CAUTION SIGNS CAN ALERT SOLDIERS TO DANGER AND PROMOTE A SAFER WORKPLACE.

CAUTION
HAZARDOUS
MATERIAL
STORAGE AREA



THE SIGNS ON THE NEXT PAGES ARE BLACK AND YELLOW. EXCEPT FOR THE FIRE EXTINGUISHER SIGN, WHICH IS RED AND WHITE.

FLIP THE PAGE TO FIND OUT MORE...



PS MORE

CAUTIONHEARING
PROTECTION
REQUIRED**CAUTION**HEARING
PROTECTION
REQUIRED
IN THIS AREA**CAUTION**EYE
PROTECTION
REQUIRED**CAUTION**DO NOT
OPERATE
WITHOUT EYE
PROTECTION**CAUTION**WATCH
YOUR
STEPTHESE SIGNS
ARE 10 X 14
INCHES...**Legend**

NSN 9905-

CAUTION Hearing Protection Required	01-100-8205
CAUTION Hearing Protection Required In This Area	01-031-1247
CAUTION Eye Protection Required	01-100-8203
CAUTION Do Not Operate Without Eye Protection	01-100-8204
CAUTION Watch Your Step	01-054-0450*

CAUTION**HAZARDOUS
MATERIAL
STORAGE AREA**These
are
7 x 10-in
signs**CAUTION**HAZARDOUS/TOXIC
CHEMICALS ARE USED IN
THIS PLACE. MATERIAL
SAFETY DATA SHEETS
ARE AVAILABLE IN THE
SUPERVISOR'S OFFICE**CAUTION****RESPIRATOR
REQUIRED IN
THIS AREA****Legend**

NSN 9905-

CAUTION Hazardous Material Storage Area	01-342-4851*
CAUTION Hazardous/Toxic Chemicals Are Used In This Work Place. Material Safety Data Sheets Are Available In The Supervisor's Office.	01-342-4857*
CAUTION Respirator Required In This Area	01-342-4853*

*These NSNs are not on the AMDF.

Order them on DD Forms 1348-6 and put "NSN not on AMDF" in the REMARKS block.

CAUTIONDO NOT OPERATE
MACHINERY
WITHOUT GUARDS**CAUTION**OPEN DOOR
SLOWLY**CAUTION**HAZARDOUS
MATERIAL
STORAGE AREA**CAUTION**WEAR GOGGLES
WHEN USING
THIS MACHINETHESE ARE
3 X 5-IN
SIGNS.**Legend**

NSN 9905-

CAUTION Do Not Operate Machinery Without Guards	01-342-4854*
CAUTION Open Door Slowly	01-342-4852*
CAUTION Hazardous Material Storage Area	01-342-4859*
CAUTION Wear Goggles When Using This Machine	01-342-4855*

*These NSNs are not on the AMDF. Order them on DD Forms 1348-6 and put "NSN not on AMDF" in the REMARKS block.

Legend

Size in inches

NSN 9905-

CAUTION Eye Protection Required In This Area	7 x 17	01-210-5241
Fire Extinguisher	10 x 14	01-195-7682

CAUTION**EYE PROTECTION
REQUIRED
IN THIS AREA**Here are
two more
signs that
contribute
to safety:

If you have noisy gear, slap this black and yellow caution plate on it: CAUTION High Intensity Noise Hearing Protection Required. Get it with NSN 9905-00-198-2728. The plate is 4.6 x 2.13 inches and comes with an adhesive backing.

For more information on using signs and symbols in dangerous areas, see OSHA Regulation 29 CFR 1910, Subpart J. You'll find it at the OSHA website at:

<http://www.osha.gov/>